

# 2014.03.06 - Helium Polish version 5.6.34.1

Release contains:

File	Version
HeliimPolish.exe	5.6.34.1

In this version we have fixed following bugs:

1. This version doesn't search additional contours for Groove method.
2. Rx section for search of groove projection is optimal. Motor Rx is rotated on -9 degrees before start of scanning.
3. Correct saving of c2v from menu Start/Main/Export c2v file... In previous version saving was not correct.